



99-9233

Replaces: 84219-3L000
NUT-ENGINE UNDER COVER
Plastic, Black

Screw: M6-1.0, Flange:20MM,
Height: 9.5MM

Hyundai Accent, Azera, Elantra, Equus, Genesis,
Santa Fe, Sonata, Tucson 2008/
Kia Forte, Optima, Rio, Sorento,
Sportage 2011-2015
UNIT PACKAGE 25



17-9346

Replaces: 87715-3K000
RETAINER-WAIST MOULDING
Plastic w/Seal, White

Slot: 8MM, Top Hd: 9 x 11MM,
Stem Lgth: 10MM, O/L: 12.5MM
Hyundai Azera, Equus, Genesis, Sonata,
Tucson, Veloster 2005/
Kia Soul 2014/
UNIT PACKAGE 25



APPLICATION UPDATES NOTED IN BOLD

Catalog Page 291

87-6234

Replaces: 12101898, PT168,
1U2Z-14S411-FA,
1U2Z-14S411-BCA, WPT-107,
WPT-148, **5102410AA**
REPAIR HARNESS-HEADLAMP
SOCKET
for 9005 (HB3), 9145 (H10) &
H4352, 9005 (H12)
High Beam, 2-10" Leads,
18 Ga. Wire
GM '86/, Ford, Chrysler,
Fog Lamps Ford Expedition &
Lincoln LS '99/
UNIT PACKAGE 5

Catalog Page 292, 315

89-6653

Replaces: 12043215, 88862217,
19299616, PT2298, **PT2856**,
3U2Z-14S411-VZA,
3U2Z-14S411-VZB, WPT-781,
WPT-952, **5017113AA**
REPAIR HARNESS-SOCKET
ASSEMBLY HALOGEN BULB
for Bulb #s 862, 886, 881, 889,
896, 894, 898,
H8, H11, **H16**
2-7" 18 Ga. Leads
GM '83/, Ford 2005/, **Chrysler**
UNIT PACKAGE 1

Catalog Page 310, 321, 327

96-7594

Replaces: 12085485, PT107,
88862267, PT2348,
3U2Z-14S411-NZA,
3U2Z-14S411-SFA, WPT-494,
WPT-564, **5019910AA**
REPAIR HARNESS,
BACK UP LAMP SWITCH
Switch #23049569, D2220A
Speed Sensor, IAC Valve
& Various Wiring
2-12 Ga. SXL 8" Leads
GM Cars & Trucks '71/,
Ford Mustang 2001-2014,
Chrysler '94/
UNIT PACKAGE 1

Catalog Page 329

99-8396

Replaces: 3U2Z-14S411-HVA,
3U2Z-14S411- CDA, WPT-657,
WPT-304, 88861090, PT2156,
5014002AA
REPAIR HARNESS-WINDSHIELD
WASHER PUMP, IAC VALVES,
COOLANT TEMP SENSOR,
TRANS SPEED SENSOR
Pump #F6SZ-17664-BA,
F6SU-17664-DA, WG300
IAC Valve #'s F65Z-9F715-EB,
F75Z-9F715-AB
2-16 Ga. TXL 8" Leads
Ford Cars & Trucks '95/,
Chrysler '97/
UNIT PACKAGE 1

Catalog Page 354

99-8974

Replaces: 3U2Z-14S411-VA, WPT-
206, 3U2Z-14S411-HYA, WPT 284,
3U2Z-14S411-HYB, WPT-989,
5014003AA
REPAIR HARNESS-COOLANT TEMP
SENSOR, **AIR TEMP SENSOR,**
BRAKE FLUID LEVEL SENSOR
Sensor#F5AZ-12A648-AB, DY719,
3F1Z-12A648-A, DY1144
2-14ga TXL 8" Leads
Ford Cars & Trucks '95/,
CHRYSLER '97/
UNIT PACKAGE 1

*Catalog Page 304, 311, 321,
322, 340*

96-7530

Replaces: 12102747, PT374,
88862226, PT2307, **13580106,**
PT2625
3U2Z-14S411-CJAA, WPT-692
REPAIR HARNESS-A/C PRESSURE
CYCLING SW-#25604949,
WHEEL SPEED SENSOR, EGR VALVE
CONTROL &
WINDSHIELD WASHER PUMP
#22127653,
BACKUP LAMP SWITCH,
FOG LAMP
2-16 Ga. (GXL) Leads 8" Length
GM Car & Truck '87/, Ford 2002/,
SAAB
UNIT PACKAGE 1

Catalog Page 308

99-9018

Replaces: 89046837, PT2057,
13585849, PT2787
REPAIR HARNESS-ALTERNATOR
2-14ga TXL 8" Leads
GM 2004/
UNIT PACKAGE 1